

Florida Licensed HI4716
Florida Licensed CGC1514988
InterNACHI Certified Inspector 14080806
www.fdaluma.com

Home Inspection Report

Fernando Aluma

Property Address:

Lakeside Cir Sunrise FL 33326



Front Elevation

Aluma Home Inspections

Fernando Aluma HI 4716 5401 Madison St Hollywood FL 33021 786-286-3166

Table of Contents

541 Lakeside Cir Page 2 of 36

Date: 2/18/2018	Time: 02:00 PM	Report ID:
Property: Lakeside Cir Sunrise FL 33326	Customer: Fernando Aluma	Real Estate Professional: Monica Mendes

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

<u>Inspected (IN)</u> = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

HOME INSPECTION DEFINITION AND LIMITATIONS

<u>Definition:</u> A Home inspection is a non invasive, limited visual examination of the existing conditions, systems and materials of the property.

Limitations:

- 1) Inspections are done over **OPEN VIEWABLE ACCESSIBLE** areas of walls, floors, ceilings, windows, doors, water heaters, closets, garages, etc. Furnished rooms, stuffed closets, storages or garages **ADD MORE LIMITATIONS** to the inspection since furniture, household goods, clothes, storage stuff, carpets, paintings etc. cover areas of walls, floors, ceilings, etc. that can not be inspected without removing these obstacles.
- 2) We are **NOT LIABLE** for damage on hidden or inaccessible walls, floors, ceilings, doors, windows, etc. Example: apparent mold in stuffed closet walls, rot baseboards or damaged wood / tile flooring behind / beneath sofas, etc.
- 3) **WE DO NOT** remove furniture, household goods, clothes, carpets, paintings, etc to access to hidden areas for liability reasons.
- 4) **NO WARRANTY** is given over any appliance(s), Air Conditioning system(s), electrical or mechanical equipment(s), Water Heater(s), Fan(s), Refrigerator(s), etc. after inspection is done.
- 5) MOLD: We are NOT LIABLE for pre-existing MOLD microorganisms (FUNGI) hidden on Roofs, Walls, Floors, Ceilings, etc. as result of old leaks not detected during inspection.

Standards of Practice:In Attendance:Type of building:InterNACHI National Association of CertifiedCustomerSingle Family (1 story)Home Inspectors

Approximate age of building:Temperature:Weather:30YearsOver 65Cloudy

541 Lakeside Cir Page 3 of 36

Ground/Soil surface condition: Rain in last 3 days:

Dry No



541 Lakeside Cir Page 4 of 36

1. Roofing / Chimneys / Roof Structure and Attic

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

Styles & Materials

Viewed roof covering from: Roof Covering: Roof-Type:

Walked roof Modified bitumen membrane Gable

Asphalt/Fiberglass Shingles

Sky Light(s): Roof Ventilation: Method used to observe attic:

None Soffit Vents From entry

Roof Structure:Ceiling Structure:Attic info:Engineered wood trusses2X4Attic access

Attic Insulation:

Fiberglass

		IN	NI	NP	RR
1.0	Roof Coverings	•			•
1.1	Flashings	•			
1.2	Skylights, Chimneys and Roof Penetrations	•			
1.3	Roof Drainage Systems (gutters and downspouts)	•			•
1.4	Insulation in Attic	•			
1.5	Roof structure and Attic	•			
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

1.0 (1) Good Condition. Roofing permit done in May 23, 2005



Shingle roofing

541 Lakeside Cir Page 5 of 36

1.0 (2) Defective


Rolled roofing shows some deterioration at the rear of home. I recommend to protect the rolled roofing with a waterproofing elastomeric sealant coating to prevent leaks and extend remaining life. A qualified licensed contractor should inspect and repair or replace as needed.



- 1.1 Good Condition
- 1.2 Good Condition
- 1.3 (1) Good Condition

1.3 (2) Defective

The gutters are full of debris in areas and needs to be cleaned. The debris in gutters can also conceal rust, deterioration or leaks that are not visible until cleaned, and I am unable to determine if such conditions exist.





541 Lakeside Cir Page 6 of 36



1.4 Good Condition



1.5 Good condition

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

541 Lakeside Cir Page 7 of 36

2. Exterior

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

Styles & Materials

Siding Material:Exterior Entry Doors:Appurtenance:Stucco on masonryImpact glass doorCovered porch

Steel

Driveway: Windows:

Asphalt Single hung. Impact rated

		IN	NI	NP	RR
2.0	Structure	•			
2.1	Wall Cladding, Flashing and Trim	•			
2.2	Doors (Exterior)	•			
2.3	Windows	•			
2.4	Eaves, Soffits and Fascias	•			•
2.5	Grading, Drainage and Driveways	•			
2.6	Plumbing Water Faucets (hose bibs)	•			
2.7	Outlets (Exterior)	•			
2.8	Fence	•			•
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

541 Lakeside Cir Page 8 of 36

Comments:

2.0 Good condition





Front Elevation



Right Elevation




Rear Elevation

Left Elevation

541 Lakeside Cir Page 9 of 36

2.1 Good Condition

2.2 Good Condition. Impact rated





Impact rated door

Impact rated door

2.3 Good Condition. Impact rated





541 Lakeside Cir Page 10 of 36

2.4 Defective

A gap between the fascia and roof sheathing exists which allows insects or bees to enter attic at the rear of home . A qualified licensed contractor should inspect and repair or replace as needed.



- 2.5 Good condition
- 2.6 Good Condition
- **2.7** Good Condition

2.8 Defective

Metal fence shows some damage at the rear of lot. A qualified licensed contractor should inspect and repair or replace as needed.



541 Lakeside Cir Page 11 of 36

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

3. Garage

Styles & Materials							
Garage Door Type:	Garage Door Material:	Auto-opener Manufac	turer	:			
One automatic	e automatic Metal not impact CHAMBERLAIN						
			IN	NI	NP	RF	
3.0 Garage Ceiling			•			•	
1 Garage Walls (Including Firewall Separation)		•					
.2 Garage Floor			•			•	
3.3 Garage Door (s)	0.2-		•				
3.4 Occupant Door from Gar	rage to inside home	tis	•				
3.5 Garage Door Operators	(Report whether or not doors will reverse when r	net with resistance)	•				
3.6 Outlets wall switches and	d fixtures		•				
3.7 Windows		1 3 1	•				

IN

NP RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

3.0 Defective

The Texture on the ceiling reveals a light stain which appears from a water leak. Stain appears old at the garage. While this damage is cosmetic, it needs to be repaired. A qualified person should repair or replace as needed.



541 Lakeside Cir Page 12 of 36

3.1 Good Condition


3.2 Defective

The concrete floor of garage is peeling paint. A qualified licensed contractor should inspect and repair or replace as needed.



3.3 Good Condition







Metal garage door. Not impact

- 3.4 Good Condition
- 3.5 Good Condition
- **3.6** Good condition
- 3.7 Good condition

541 Lakeside Cir Page 13 of 36

4. Kitchen Components and Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

Styles & Materials

Dishwasher Brand: Disposer Brand: Exhaust/Range hood:

SAMSUNG UNKNOWN SAMSUNG

Range/Oven: Built in Microwave: Cabinetry:

SAMSUNG SAMSUNG Wood

Countertop:Refrigerator:Dryer brand:GraniteSAMSUNGWHIRLPOOL

Washer Brand:

WHIRLPOOL

		IN	NI	NP	RR
4.0	Ceiling	•			
4.1	Walls	•			
4.2	Floor	•			
4.3	Pantry/Closet Doors	•			
4.4	Windows	•			
4.5	Counters and a representative number of Cabinets	•			•
4.6	Plumbing Drain and Vent Systems	•			
4.7	Plumbing Water Supply Faucets and Fixtures	•			
4.8	Outlets Wall Switches and Fixtures (Representative number)	•			•
4.9	Dishwasher	•			
4.10	Ranges/Ovens/Cooktops	•			
4.11	Range Hood	•			
4.12	Food Waste Disposer	•			
4.13	Microwave Cooking Equipment	•			
4.14	Refrigerator	•			
4.15	Laundry	•			
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

541 Lakeside Cir Page 14 of 36

Comments:

4.0 Good Condition

4.1 Good Condition

4.2 Good Condition

4.3 Good Condition

4.4 Good Condition

4.5 Defective

Drawer track does not work smoothly (left of sink). This is a cosmetic issue for your information. Recommend repair or replace as necessary.



541 Lakeside Cir Page 15 of 36

- **4.6** Good condition
- **4.7** Good condition

4.8 Defective

At least One GFCI (Ground Fault Circuit Interrupter) outlet at the kitchen did not work or there is no power to outlet. Electrical issues are considered a hazard until repaired. I recommend repair as needed.


Estimated cost to repair or replace around \$50-\$150. Call contractors for estimate.



541 Lakeside Cir Page 16 of 36

- 4.9 Good condition
- 4.10 Good condition
- 4.11 Good condition
- 4.12 Good condition
- 4.13 Good condition
- 4.14 Good condition

4.15 Good condition



The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report

5. Rooms

Sheetrock

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

Styles & Materials

Tile

Ceiling Materials: Wall Material: Floor Covering(s):

Sheetrock


Interior Doors: Window Types:

Hollow core Single-hung

541 Lakeside Cir Page 17 of 36

		IN	NI	NP	RR
5.0	Ceilings	•			
5.1	Walls	•			
5.2	Floors	•			
5.3	Steps, Stairways, Balconies and Railings	•			
5.4	Doors (Representative number)	•			
5.5	Windows (Representative number)	•			
5.6	Outlets, Switches and Fixtures (Representaive number)	•			•
5.7	Closets	•			
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace



541 Lakeside Cir Page 18 of 36

Comments:

5.0 Good condition

5.1 Good condition

5.2 Good condition

5.3 Good condition

5.4 Good condition

5.5 Good condition

5.6 Defective

The ceiling fan has the switch chain stuck at the Dining room. A qualified licensed contractor should inspect and repair or replace as needed.

ion of Cerr



5.7 Good condition

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

6. Bathroom and Components


Styles & Materials

Exhaust Fans:

Fan only

541 Lakeside Cir Page 19 of 36

		IN	NI	NP	RR
6.0	Counters and Cabinets	•			
6.1	Doors (Representative number)	•			
6.2	Windows	•			
6.3	Plumbing Drain, Waste and Vent Systems	•			
6.4	Plumbing Water Supply and Distribution Systems and Fixtures	•			
6.5	Outlets Switches and Fixtures (Representative number)	•			•
6.6	Exhaust fan	•			
6.7	Walls	•			
6.8	Floors	•			
6.9	Ceilings	•			
6.10	Outlets Switches and Fixtures	•			
		IN	NI	NP	RR





541 Lakeside Cir Page 20 of 36

Comments:
6.0 Good condition
6.1 Good condition
6.2 Good condition
6.3 Good condition
6.4 Good condition
6.5 Defective
At least One GFCI (Ground Fault Circuit Interrupter) outlet at the hall bath did not work or there is no power to outlet. Electrical issues are considered a hazard until repaired. I recommend repair as needed.
6.6 Good condition
6.7 Good condition
6.8 Good condition
6.9 Good condition
6.10 Good condition

541 Lakeside Cir Page 21 of 36

7. Structural Components

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

		IN	NI	NP	RR
7.0	Foundations, Basements and Crawlspaces (Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components.)	•			
7.1	Walls (Structural)	•			
7.2	Columns or Piers	•			
7.3	Floors (Structural)	•			
7.4	Ceilings (Structural)	•			
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

		 	_		L	
• .		m		m	ts:	
_	$\mathbf{A} \mathbf{U}$	 	_			

7.0 Good condition	2
7.1 Good condition	
7.2 Good condition	
7.3 Good condition	
7.4 Good condition	THE TOTAL OF THE PARTY OF THE P

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

8. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.

541 Lakeside Cir Page 22 of 36

Styles & Materials

Water Source: Water Filters: Plumbing Water Supply (into home):

Public None Copper

Plumbing Water Distribution (inside Washer Drain Size: Plumbing Waste Line:

home): 1 1/2" Diameter (undersized) PVC

Copper

Water Heater Power Source: Water Heater Capacity: Water Heater Manufacturer:

Electric 40 Gallon (1-2 people) GE

Water Heater Location:

Garage

		IN	NI	NP	RR
8.0	Plumbing Drain, Waste and Vent Systems	•			
8.1	Plumbing Water Supply and Distribution Systems and Fixtures	•			
8.2	Hot Water Systems, Controls, Chimneys, Flues and Vents	•			
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace



541 Lakeside Cir Page 23 of 36

Comments:

- 8.0 Good condition
- **8.1** Good condition
- 8.2 Good Condition. Manufactured year 2011

NOTE:

Tank water heaters: Due to physical location at home, usually on laundry wall corners, closets, below stairs, etc. The tank water heater is impossible to get visually inspected 100%, there are always hidden areas unable to access for inspection. In most of the cases 50-75% of the tank perimeter is unable to check. Due to these limitations the inspection is limited to the exposed area.





Manufactured year 2011

Water Heater

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

541 Lakeside Cir Page 24 of 36

9. Electrical System

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.

Styles & Materials

Electrical Service Conductors: Panel capacity: Panel Type:

Overhead service 150 AMP Circuit breakers

Electric Panel Manufacturer: Branch wire 15 and 20 AMP: Wiring Methods:

ITE Copper Romex

		IN	NI	NP	RR
9.0	Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage	•			
9.1	Connected Devices and Fixtures (Observed from a representative number operation of ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls)	•			
9.2	Polarity and Grounding of Receptacles within 6 feet of interior plumbing fixtures, and all receptacles in garage, carport and exterior walls	•			
9.3	Operation of GFCI (Ground Fault Circuit Interrupters)	•			
9.4	Location of Main and Distribution Panels	•			
9.5	Smoke Detectors	•			
		IN	NI	NP	RR


IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace



Comments:

9.0 Good condition





Open Panel

Front Panel

- 9.1 Good condition
- 9.2 Good condition
- 9.3 Good condition
- **9.4** Good condition
- 9.5 Good condition

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

10. Heating / Central Air Conditioning

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

Styles & Materials

541 Lakeside Cir Page 26 of 36

Heat Type: Energy Source: Number of Heat Systems (excluding

Heat Pump Forced Air (also provides cool Electric wood):

air) One

Ductwork: Filter Type: Cooling Equipment Type:

Insulated Disposable Heat Pump Forced Air (also provides warm

air)

Cooling Equipment Energy Source: Central Air Manufacturer: Number of AC Only Units:

Electricity RHEEM One

		IN	NI	NP	RR
10.0	Cooling and Air Handler Equipment	•			
10.1	Normal Operating Controls	•			
10.2	Presence of installed cooling source in each room	•			
		IN	NI	NP	RR

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Comments:

10.0 Good condition. Manufactured year 2012

The system worked as expected when tested and appeared to be serviceable at the time of the inspection. As with all mechanical equipment, the unit may fail at any time without warning. The inspector cannot determine future failures.

Recommendation: To keep a good system performance and efficiency I recommend a HVAC contractor to service the whole system including Condenser, Air handler, gas, thermostat, etc. and repair or replace as needed.





2012 AC condenser 2012 AC condenser lab

541 Lakeside Cir Page 27 of 36



2012 Air handler

10.1 Good condition

10.2 Good condition

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.



541 Lakeside Cir Page 28 of 36

General Summary



Florida Licensed HI4716
Florida Licensed CGC1514988
InterNACHI Certified Inspector 14080806
www.fdaluma.com

Aluma Home Inspections

5401 Madison St Hollywood FL 33021 786-286-3166

Customer
Alberto & Natalia Alvarez

Address 541 Lakeside Cir

Sunrise FL 33326

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

1. Roofing / Chimneys / Roof Structure and Attic

1.0 Roof Coverings

Inspected, Repair or Replace

(1) Good Condition. Roofing permit done in May 23, 2005

541 Lakeside Cir Page 29 of 36



Shingle roofing

(2) Defective

Rolled roofing shows some deterioration at the rear of home. I recommend to protect the rolled roofing with a waterproofing elastomeric sealant coating to prevent leaks and extend remaining life. A qualified licensed contractor should inspect and repair or replace as needed.



1.3 Roof Drainage Systems (gutters and downspouts)

Inspected, Repair or Replace

- (1) Good Condition
- (2) Defective

The gutters are full of debris in areas and needs to be cleaned. The debris in gutters can also conceal rust, deterioration or leaks that are not visible until cleaned, and I am unable to determine if such conditions exist.

541 Lakeside Cir Page 30 of 36





2. Exterior

2.4 **Eaves, Soffits and Fascias**

Inspected, Repair or Replace

Defective

A gap between the fascia and roof sheathing exists which allows insects or bees to enter attic at the rear of home . A qualified licensed contractor should inspect and repair or replace as needed.

Page 31 of 36 541 Lakeside Cir



2.8 Fence

Inspected, Repair or Replace

Defective

Metal fence shows some damage at the rear of lot. A qualified licensed contractor should inspect and repair or replace as needed.



3. Garage

3.0 Garage Ceiling

Inspected, Repair or Replace

Defective

The Texture on the ceiling reveals a light stain which appears from a water leak. Stain appears old at the garage. While this damage is cosmetic, it needs to be repaired. A qualified person should repair or replace as needed.

541 Lakeside Cir Page 32 of 36



3.2 Garage Floor

Inspected, Repair or Replace

Defective

The concrete floor of garage is peeling paint. A qualified licensed contractor should inspect and repair or replace as needed.



4. Kitchen Components and Appliances

4.5 Counters and a representative number of Cabinets

Inspected, Repair or Replace

Defective

Drawer track does not work smoothly (left of sink). This is a cosmetic issue for your information. Recommend repair or replace as necessary.

541 Lakeside Cir Page 33 of 36



4.8 Outlets Wall Switches and Fixtures (Representative number)

Inspected, Repair or Replace

Defective

At least One GFCI (Ground Fault Circuit Interrupter) outlet at the kitchen did not work or there is no power to outlet. Electrical issues are considered a hazard until repaired. I recommend repair as needed.

Estimated cost to repair or replace around \$50-\$150. Call contractors for estimate.



5. Rooms

5.6 Outlets, Switches and Fixtures (Representaive number)

Inspected, Repair or Replace

Defective

The ceiling fan has the switch chain stuck at the Dining room. A qualified licensed contractor should inspect and repair or replace as needed.

541 Lakeside Cir Page 34 of 36



6. Bathroom and Components

6.5 Outlets Switches and Fixtures (Representative number)

Inspected, Repair or Replace

Defective

At least One GFCI (Ground Fault Circuit Interrupter) outlet at the hall bath did not work or there is no power to outlet. Electrical issues are considered a hazard until repaired. I recommend repair as needed.





Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.





541 Lakeside Cir Page 36 of 36